

Tuesday, 22nd March, 2016

Notification: Unismart update for Samsung MLT-D203 replacement chip

To Apex cooperative partners,

First of all, we would like to thank you for your long-term trust and support in Apex products, which build a solid foundation for our cooperation.

Recently, Samsung updated hardware for its newly manufactured printers, leading to the replacement products cannot work normally (please refer to Apex' s "Replacement Chips for Samsung MLT-D203 Series Product Update Notification" for detailed information). Apex has conducted an in-depth analysis for it and decided to release new version replacement chip for use in Samsung MLT-D203 series, which can be used in all printers of Samsung MLT-D203 series in the market. Moreover, Unismart simultaneously updated to V3.24.8, customers therefore can reset their Samsung MLT-D203 replacement chips with Unismart version V3.24.8 so as to continue using the chips.

Apex will launch the following new version products, please contact your sales manager for more information.

Models involved:

U Character	APEX Code	OEM Code	Color	Yield	Region	For Use in Printer
OS3	ALS-D203S	MLT-D203S	BK	3K	EXP/EUR DOM/MEA/ CHN	Samsung SL-M3320/3820/4020
	ALS-D203L	MLT-D203L	BK	5K		Samsung M3370/3870/4070
	ALS-D203E	MLT-D203E	BK	10K		Samsung SL-M3820/4020 Samsung M3870/4070

We thank you for your support and cooperation. As always, Apex will dedicate to R&D to provide you a comprehensive and reliable chip solution.

Sincerely yours,

Apex Microelectronics CO., LTD.